

126 Anderson Road, Wanaka

\bigcirc Your property

Property
Tenants
Rent
Lease ends

126 Anderson Road, Wanaka \$500.00 per week 17/11/2022

$\hat{\equiv}$ This inspection

Inspected on	Inspected by	Report created on
21 September 2022	Melanie Moore	21 September 2022

^{2°} Comments

Area	Condition	Comments	Photos
Exterior	GOOD	Cladding and gutters are fine, no spider webs.	1-3
Grounds and Gardens	GOOD	Lawns and garden beds are tidy. Fruit trees have been pruned by the gardener and flowering. Irrigation timer has a few cracks, would you like that replaced?	4-8
Kitchen/meals	GOOD	No leaks from under the sink. Oven, cook top and extractor are clean.	9-12
Lounge room	GOOD	Few wear and tear chips and marks. Chimney swept Feb 22. Heat pump serviced June 22.	13-15
Bedroom 1	GOOD	Nothing to report. Windows open for ventilation.	16-17
Bedroom 2	GOOD	Nothing to report. Windows open for ventilation.	18-19
Bathroom	GOOD	Clean and tidy. Have asked tenant to clean extractor cover. Shower trap is broken, would you like me to organise a new one?	20-21
Laundry	GOOD	No leeks reported.	22-23
Smoke Alarms	GOOD	3x Smoke Alarms - Location Bedroom 1 & 2 and office downstairs. All expire 2028. All Tested and working.	24-26
Stairway	GOOD	Alistair looking at door today. There is a spider nest on the high ceiling, we will arrange for this to be removed.	27-28
Garage	GOOD	Nothing to report.	
Water Toby / Power Board	GOOD	Power board located in garage. 2x water toby - 1x in garden bed near driveway - 1 near front door driveway. Filter on main Toby.	29-31

Bayleys Property Management Level 1, 41 Shotover Street, Queenstown, 9348

$\stackrel{\scriptstyle oo}{\scriptstyle \sim}$ General comments

As usual, the house was looking good for the inspection. Rent is paid on time, please see notes regarding maintenance issues.

The builder is going to look at the door today and the tenant will give the extractor cover in the bathroom a good clean.

I will keep in touch with the tenants about their lease ending in November, at this stage it sounds like they won't renew, however will keep you updated.

Please note that inspections are carried out visually only as property managers hold no other qualification or representation other than that of a Property Agent.





Inspection Photos

Routine Inspection Report

126 Anderson Road, Wanaka

1 to 4 of 31 photos



1. Exterior 21/09/22 at 02:20 PM

2. Exterior 21/09/22 at 02:21 PM



3. Exterior 21/09/22 at 02:21 PM



4. Grounds and Gardens 21/09/22 at 02:21 PM

Bayleys Property Management Level 1, 41 Shotover Street, Queenstown, 9348



Bayleys Property Management Level 1, 41 Shotover Street, Queenstown, 9348






126 Anderson Road, Wanaka

5 to 8 of 31 photos







7. Grounds and Gardens 21/09/22 at 02:23 PM



6. Grounds and Gardens 21/09/22 at 02:22 PM



8. Grounds and Gardens 21/09/22 at 02:23 PM



Photos continued...



Routine Inspection Report

126 Anderson Road, Wanaka

Photos continued...

9 to 12 of 31 photos






9. Kitchen/meals 21/09/22 at 02:25 PM



11. Kitchen/meals 21/09/22 at 02:25 PM





12. Kitchen/meals 21/09/22 at 02:26 PM





Routine Inspection Report


126 Anderson Road, Wanaka

Photos continued...

13 to 16 of 31 photos



13. Lounge room 21/09/22 at 02:26 PM



14. Lounge room 21/09/22 at 02:36 PM



15. Lounge room 21/09/22 at 02:38 PM



16. Bedroom 1 21/09/22 at 02:27 PM



Photos continued...



17. Bedroom 1 21/09/22 at 02:27 PM

Routine Inspection Report

126 Anderson Road, Wanaka

17 to 20 of 31 photos



18. Bedroom 2 21/09/22 at 02:27 PM



19. Bedroom 2 21/09/22 at 02:38 PM



20. Bathroom 21/09/22 at 02:39 PM



Photos continued...



21. Bathroom 21/09/22 at 02:40 PM



23. Laundry 21/09/22 at 02:29 PM

Routine Inspection Report

126 Anderson Road, Wanaka

21 to 24 of 31 photos



22. Laundry 21/09/22 at 02:29 PM



24. Smoke Alarms 21/09/22 at 02:32 PM



Routine Inspection Report

126 Anderson Road, Wanaka

25 to 28 of 31 photos






25. Smoke Alarms 21/09/22 at 02:33 PM



27. Stairway 21/09/22 at 02:30 PM



26. Smoke Alarms 21/09/22 at 02:33 PM



28. Stairway 21/09/22 at 02:32 PM

Bayleys Property Management Level 1, 41 Shotover Street, Queenstown, 9348

Routine Inspection Report

126 Anderson Road, Wanaka

29 to 31 of 31 photos



30. Water Toby / Power Board 21/09/22 at 02:34 PM



31. Water Toby / Power Board 21/09/22 at 02:35 PM



Photos continued...



29. Water Toby / Power Board 21/09/22 at 02:33 PM



126 Anderson Road, Wanaka

$\stackrel{\scriptstyle <}{\scriptstyle \sim}$ Maintenance Requests

Title	Description
Irrigation timer	Irrigation timer cracked
Shower trap	Shower trap broken

